DIVIDE COUNTY

Planning Unit 094: AML Printout #238: T161N, R102W, Section 13, NE, SE Planning Unit 094: AML Printout #241: T161N, R102W, Section 14, SE

Additional Legal Location: No part section

Name: Owner:

No data

Category: No data

Type: Underground, slope

Thickness

Overburden: Coal Seam: Mined: Source:

Cultural Resource Site Number: Not formally recorded

Basic Data (excerpted from primary sources):

Leonard et al. (1925) indicates, "Coal has been mined here on a small scale for many years, the bed being exposed or occurring near the surface in secs. 13 and 14, T.161N., R.102W... in mining the coal slopes are driven into the bed..." However, Leonard et al. (1925) do not provide mine names, and no further information could definitely be correlated with this information from Leonard et al. (1925).

Descriptive information pertaining to this mine is included in:

{source:year(pages)]

Not applicable

Notes:

Leonard at al. (1925) do not provide part sections for the reference to slope mining in Sections 13 and 14; therefore, it is not known if the mining referred to by Leonard et al. (1925) occurred at the above Planning Units and AML locations, or if it occurred in other portions of Sections 13 and 14.

The Mathieson Coal Mine also is located at Planning Unit 094, AML location 241 (T161N, R102W, Section 14, SE).

Sources (primary and secondary):

Leonard et al.:1925(80)